



IDS821

High Accuracy Crane Scale

Function:

Zero Overload Alarm/ Record
 Tare In/ Tare Out
 Digital Calibration
 Hold
 Low Voltage Alarm
 Battery Supervision
 Tare Set
 Resolution Switch
 Anti-motion Set
 Auto-off Set

Specification :

Accuracy Class	OIML III
Tare Range	100%F.S.
Zero Range	4%F.S.
Safe Overload	120%F.S.
Ultimate Overload	500%F.S.
Overload Alarm	100%F.S.+9e
Battery	6V/10Ah
Battery Life	>80 hour
Adaptor	9V/1500mA
Remote Distance	10m



Capacity and parameter

Max.cap	Min.cap	Division
10t	100kg	5kg
15t	100kg	5kg
20t	200kg	10kg
30t	200kg	10kg
50t	400kg	20kg